



www.unconventionalsolutions.biz

Project: Church Steeple Roof Line Repair



The Problem

The church was having issues with moisture in the steeple at the roof line and it was causing problems with the overhead lighting as well.

The church was looking for an effective and long lasting repair solution that would prevent the moisture from doing any further damage.

The church was also interested in saving time with a solution that is easy to apply.



The Solution

USI had the solution the church needed. A viscoelastic sealant and wrap were used to repair the steeple roof line and prevent moisture from causing further damage.

The viscoelastic sealant was used to seal the area where the base of the steeple meets the roof. Then the sealant was then covered with a viscoelastic wrap for added protection.

The church was very happy with the outcome of the project and with how easy it was to use and apply our products.



Unconventional Solutions, Inc.
527 Union St.
Milford, MI 48381
(248) 685-7580
www.unconventionalsolutions.biz