



www.unconventionalsolutions.biz

Project: Country Club Pool Area



The Problem

The concrete of the surrounding area of this pool was badly cracked and pitted.

The owner of the country club needed the concrete repaired and coated with a material that could withstand the chemicals of the pool water.

Solution

The concrete was given a profile and repaired with Grano-Tech.

The entire area to be coated was primed with Uni-Tech GP and then coated with two coats of Floor-Tech WB. The Floor-Tech WB was tinted from light grey to the green you seen to the right.

Note: When using Floor-Tech WB on wet slippery surfaces, grit should be added to the top coat.



Unconventional Solutions, Inc.
527 Union St.
Milford, MI 48381
(248) 685-7580
www.unconventionalsolutions.biz