



www.unconventionalsolutions.biz

Project: Gas Holder



The Problem

The gas holder had been allowed to deteriorate into a very bad condition. There was extensive rusting and after grit blasting, 50-60 holes had appeared in the lower third section. The gasometer was in need of a total upgrade.

Solution

After the entire gas holder had been grit blasted, the inside was coated with one coat of Uni-Tech MC Primer and two coats of the Chemi-Tech CR reinforced system. On the outside, the holes were filled with Wall-Tech LW, then the entire surface area was coated with one coat of Uni-Tech MC Primer and two coats of the Chemi-Tech.

This was a major refurbishment and its success has resulted in more gasometers being upgraded with the same systems.



Unconventional Solutions, Inc.
527 Union St.
Milford, MI 48381
(248) 685-7580
www.unconventionalsolutions.biz