



www.unconventionalsolutions.biz

Project: Church Refurbishment



The Problem

This church had been allowed to fall into disrepair as shown by this photograph taken in 1933 highlighting the state of the church at the time.

Apart from repairing and refurbishing the walls, there was also a requirement to protect the roofs, the stucco moldings, the floors within the church, and the repairs of various timber structures internally and externally, and indeed protection of the oak doors within the building.

One of the requirements was to try and reproduce the church in its original state including reproduction of the roof color and gold finishing on the roofing sections.

Solution

Refurbishing the church was a major task and involved numerous Thortex products including Wall-Tech CWC, Grano-Tech, Uni-Tech UV, Seal-Tech AW, Timba-Tech, Metal-Tech SG, Corro-Tech GP, etc.

In total, twelve different Thortex products were used on the church and in particular, the external wall surfaces were protected with Wall-Tech FP and the roof section was protected with Uni-Tech UV supplied in a special blue color and also in a gold finish. The pictures highlighting this refurbishment speak for themselves.



Unconventional Solutions, Inc.

527 Union St.

Milford, MI 48381

(248) 685-7580

www.unconventionalsolutions.biz