

Hot Topics

March



2008

In This Issue

Pump Repair

Pumps not working to peak efficiency? Poor performance causing an energy drain and higher utility costs? Finding it more difficult to get replacement casings or impellers? **USI can help!**

Cerami Tech CR

USI Repair Lines

Call **248-684-7580** and ask about our
Ceramic Repair Systems today.



-Our **3M** Cerami-Tech CR or Cerami-Tech FG repair system gives you a durable, abrasive resistant, glass like finish on your pump casing, impellers, and other wet components or piping to increase efficiency.

-Get up to 20% performance boost from existing equipment and even up to 7% boost from **NEW** equipment! **3M** Cerami-Tech repair systems help you keep energy costs in check and increase the life of your capital investments. Call **248-685-7580** today and start saving!

Remember USI's **3M** repair line is extensive. We have all the solutions to all of your problems. **Metal and Rubber** Repair Systems, **Concrete** Repair and Protection, **Floor** Repair and Resurfacing, Emergency and Long Term **Roof** Resurfacing Systems, and **Safety** Systems.

Sincerely,

Doug Klingensmith
USI

(248)685-7580

www.unconventionalsolutions.biz

