



www.unconventionalsolutions.biz

Project: Beverage Power Plant Floor Repair



The Problem

The floor in the power plant of a major beverage manufacturer was badly damaged from constant chemical attack.

The company needed a solution that would not only adhere to strict EPA regulations, but also offer a fast and lasting solution to prevent this from happening again.

They called USI, 3M's Scotchkote Master Distributor, to look at the problem and recommend a solution.

The Solution

The average depth of the damaged concrete floor was between 1" – 2", USI repaired the concrete with Grano-Tech. A high performance repair compound, Grano-Tech, rebuilds and protects concrete while offering outstanding adhesion.

The repaired concrete was coated with Floor-Tech SP, a solvent free primer, and topped with Chemi-Tech UC.

Chemi-Tech UC is a two component coating that provides excellent and lasting protection for concrete surfaces subjected to aggressive acids and chemicals.



Unconventional Solutions, Inc.

527 Union St.

Milford, MI 48381

(248) 685-7580

www.unconventionalsolutions.biz