



www.unconventionalsolutions.biz

Project: Concrete Stairway Repair



The Problem

The project requirement was to completely repair and coat the stairway in this Recreation Area, which serves as one of the main access routes.

A heavy duty repair system was sought due to the "high wear" environment.

Solution

Thorough cleaning and roughening of the surface of the repair area was carried out before the application of a tack coat of Grano-Tech Primer. The damaged areas were then rebuilt using Grano-Tech which is our three component, solvent free, heavy duty epoxy repair mortar.

The entire surface of the concrete stairway was then coated with Floor-Tech FB.



Unconventional Solutions, Inc.

527 Union St.

Milford, MI 48381

(248) 685-7580

www.unconventionalsolutions.biz