



www.unconventionalsolutions.biz

Project: External Pipe Protection



The Problem

This pipeline crossing a river had badly corroded and was in need of urgent protection.

The pipe had been in place for many years and corrosion had occurred with regard to the supporting steelwork and the actual pipeline.

The 3M Thortex proposal involved water blasting and application of Corro-Tech GP.

Solution

The entire structure was water blasted using high pressure water cleaning to clean both the structural steelwork and the pipeline in question.

After water blasting, all steelwork and areas of pipeline were protected with one coat of Corro- Tech GP with the material being applied by brush.

Brush application ensures complete penetration and protection of the structure. This application has been a complete success for the Water Authority.



Unconventional Solutions, Inc.
527 Union St.
Milford, MI 48381
(248)685-7580
www.unconventionalsolutions.biz