



www.unconventionalsolutions.biz

Project: Floor Area- Chemical Protection



The Problem

This floor area in a chemical factory was being attacked by acids from the processes used within the factory.

The maintenance engineers required a coating which would resist the acids involved and provide long term protection to the floor in question.

Solution

The floor was thoroughly abraded and cleaned.

One coat of Floor-Tech SP Primer followed by two coats of Chemi-Tech UC were then applied. The system has provided excellent protection to the concrete and brickwork involved and has proved to be the complete solution to the customer's problems.

As a result of this success, further applications involving Chemi-Tech UC are planned throughout the chemical plant.



Unconventional Solutions, Inc.
527 Union St.
Milford, MI 48381
(248)685-7580
www.unconventionalsolutions.biz