



www.unconventionalsolutions.biz

Project: Metal Storage Tank Repair



The Problem

These bulk storage tanks have been severely damaged by corrosion. The corrosion was so bad the actual structural integrity of the tanks were threatened and immediate repair was required to prolong the service life of the tanks.

After careful consideration, the tanks were dismantled to remove the corrosion and repair the metal.

Solution

The metal tanks were blasted to remove surface contaminants. Uni-Tech MC Primer was applied to the tank; this solvent based primer provides excellent adhesion to metal substrates. Followed by two coats of Uni-Tech UV, that was applied to provide long term protection.

The company was delighted by the application because the corrosion problem has been solved and the tanks were as good as new in appearance and more importantly, performance.



Unconventional Solutions, Inc.

527 Union St.

Milford, MI 48381

(248) 685-7580

www.unconventionalsolutions.biz