



www.unconventionalsolutions.biz

Project: Parking Garage



The Problem

The asphalt floor of this car park had become badly damaged due to the high level of use. In addition, the existing coating had cracked badly due to its rigidity.

This car park was part of a prestigious hotel and it therefore needed urgent refurbishment.

Solution

The surface was first prepared by cleaning and scabbling. An asphalt system was then applied to ensure an even floor surface.

Floor-Tech FB Primer was then applied to the asphalt to ensure good adhesion. This was then over coated with Floor-Tech FB which has provided the required impact and abrasion resistance with the flexibility not to crack due to the slight movement of the asphalt.



Unconventional Solutions, Inc.
527 Union St.
Milford, MI 48381
(248) 685-7580
www.unconventionalsolutions.biz