



www.unconventionalsolutions.biz

Project: Stairway Repairs



The Problem

This building is protected by the state as a unique architectural construction. The requirement was to repair the staircase which had deteriorated badly and return it to its original appearance.

Solution

The damaged areas were rebuilt with Grano - Tech, the High performance concrete repair product, due to the heavy usage that occurred on the staircase.

The staircase was Then recoated with decorative coating systems to return it to its Original condition.



Unconventional Solutions, Inc.

527 Union St.

Milford, MI 48381

(248)685-7580

www.unconventionalsolutions.biz