



www.unconventionalsolutions.biz

Project: Tank Chime Repair



The Problem

An oil company was looking for a cost-effective and long lasting repair solution for their tank chimes. As seen in the picture, there was about an inch and a half gap that needed to be repaired and sealed.

The company was also interested in saving time with a solution that is easy to apply.



The Solution

USI was able to satisfy all the needs of this oil company by using a viscoelastic sealant and wrap.

The viscoelastic sealant was used to seal the gap at the base of the tank chime. Then the sealant was covered with a viscoelastic wrap for added protection.

The company was very pleased with our ability to deliver the product and train their employees to make the repair in house.



Unconventional Solutions, Inc.

527 Union St.

Milford, MI 48381

(248) 685-7580

www.unconventionalsolutions.biz