




[www.unconventionalsolutions.biz](http://www.unconventionalsolutions.biz)

## Project: Water Tank Repair

### The Problem

A water treatment facility had a concrete water tank with a crack that was in desperate need of repair. The facility only had eight hours to make the repair.

The company was looking for an option that would seal the leak, and save them time and money. USI recommended Viscotaq sealant because of the minimal surface prep (no sand blasting), outstanding corrosion resistance, holds back water up to 5 psi and most importantly a quick return to service.



### The Solution

While most solutions need six to eight days, sometimes longer, with a repair like this and before returning to service; USI with the help of Amcorr's Viscotaq sealant the job was done in 5 hours with absolutely no leaks.

Viscotaq sealant is designed to have permanent contact with its substrate and form a continuous waterproof protective coating. With the ability to adhere to almost any surface, makes Viscotaq sealant an ideal solutions for many water infiltration problems.



**Unconventional Solutions, Inc.**

**527 Union St.**

**Milford, MI 48381**

**(248) 685-7580**

**[www.unconventionalsolutions.biz](http://www.unconventionalsolutions.biz)**